

NTSB Identification: **OAK69F0098**
 14 CFR Part 91 General Aviation
 Event occurred Sunday, June 16, 1968 in SACRAMENTO, CA
 Aircraft: REPUBLIC RC-3, registration: N6375K

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-2391	68/6/16 TIME - 1902	SACRAMENTO, CALIF	REPUBLIC RC-3 N6375K DAMAGE-DESTROYED	CR- 0 1 0 PX- 0 0 1 OT- 0 0 0	INSTRUCTIONAL TRAINING	STUDENT, AGE 30, 32 TOTAL HOURS, 24 IN TYPE, NOT INSTRUMENT RATED.
		NAME OF AIRPORT - NATOMAS				
		TYPE OF ACCIDENT	PHASE OF OPERATION			
		ENGINE FAILURE OR MALFUNCTION	IN FLIGHT: NORMAL CRUISE			
		COLLIDED WITH: WIRES/POLES	LANDING: FINAL APPROACH			
		PROBABLE CAUSE(S)				
		PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING				
		MISCELLANEOUS ACTS, CONDITIONS - FUEL EXHAUSTION				
		COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE				
		EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND				