

NTSB Identification: **CHI66F0127**  
 14 CFR Part 91 General Aviation  
 Event occurred Sunday, August 01, 1965 in YOUNGSTOWN, OH  
 Aircraft: REPUBLIC RC-3, registration: N6175K

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-2039	65/8/1 TIME - 2000	YOUNGSTOWN OHIO	REPUBLIC RC-3 N6175K DAMAGE-SUBSTANTIAL	CR- 0 0 1 PX- 0 0 0 OT- 0 0 0	NONCOMMERCIAL PLEASURE/PERSONAL TRANSP	PRIVATE, AGE 40, 1500 TOTAL HOURS, 100 IN TYPE, NOT INSTRUMENT RATED.
		NAME OF AIRPORT - LANDSDOWN				
		TYPE OF ACCIDENT	PHASE OF OPERATION			
		ENGINE FAILURE OR MALFUNCTION	LANDING: TRAFFIC PATTERN-CIRCLING			
		COLLIDED WITH: TREES	LANDING: LEVEL OFF/TOUCHDOWN			
		PROBABLE CAUSE(S)				
		MISCELLANEOUS ACTS, CONDITIONS - FUEL EXHAUSTION				
		PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING				
		COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE				
		EMERGENCY CIRCUMSTANCES - FORCED LANDING ON AIRPORT/SEAPLANE BASE/HELIP.T.				