SEA80FYE31 Page 1 of 1

NTSB Identification: **SEA80FYE31** 14 CFR Part 91 General Aviation

Event occurred Friday, April 18, 1980 in PORT ANGELES, WA Aircraft: REPUBLIC RC-3, registration: N6470K

FILE	DATE	LOCATION	AIRCRAFT DATA					FLIGHT PURPOSE	PILOT DATA
3-0778	TIME - 10)15		PX-	0	0	2		COMMERCIAL, AGE 39, 2090 SP TOTAL HOURS, 300 IN TYPE INSTRUMENT RATED.
	NAME OF AIRPORT - FAIRCHILD DEPARTURE POINT INTENDED DESTINATION PORT ANGELES, WA VANCOUVER, BC, CANADA								
	TYPE OF ACCIDENT ENGINE FAILURE OR MALFUNCTION			PHASE OF OPERATION TAKEOFF: INITIAL CLIMB					
	WHEELS-UP PROBABLE CAUSE(S) PERSONNEL - MAINTENANCE, SERVICING, INSPECTION: INADEQUATE MAINTENANCE AND INSPECTION POWERPLANT - FUEL SYSTEM: LINES AND FITTINGS								
	MISCELLANEOUS ACTS,CONDITIONS - IMPROPERLY SECURED MISCELLANEOUS ACTS,CONDITIONS - LOOSE,PART/FITTING MISCELLANEOUS ACTS,CONDITIONS - FUEL STARVATION MISCELLANEOUS ACTS,CONDITIONS - INTENTIONAL WHEELS-UP								
	COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE EMERGENCY CIRCUMSTANCES - FORCED LANDING ON AIRPORT/SEAPLANE BASE/HELIPT. REMARKS- 11 HRS SINCE ANNUAL. LINE TO FUEL PUMP LOOSE.								