NYC68A0061 Page 1 of 1

## NTSB Identification: NYC68A0061

14 CFR Part 135 Nonscheduled operation of P AND M FLYIN\* Event occurred Wednesday, October 18, 1967 in ASHLAND, ME Aircraft: REPUBLIC RC-3, registration: N6569K

FILE	DATE LOCATIO	ON AIRCRAFT DATA	INJURIES F S M/N		PILOT DATA
2-0904	TIME - 1415	REPUBLIC RC-3 N6569K DAMAGE-DESTROYED	PX- 0 2 0 A: OT- 0 0 0	IR TAXI-PASSG	COMMERCIAL, FL.INSTR., AGE 41, 10806 TOTAL HOURS, 1200 IN TYPE, INSTRUMENT RATED.
	TYPE OF ACCIDENT COLLIDED WITH: TREE	70	PHASE OF OPERATION IN FLIGHT: NORMAL CRUISE		
	PROBABLE CAUSE(S)			GHT: NORMAL CRUISE	
	PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING PILOT IN COMMAND - CONTINUED VFR FLIGHT INTO ADVERSE WEATHER CONDITIONS  FACTOR(S) WEATHER - LOW CEILING WEATHER - RAIN WEATHER - FOG WEATHER BRIEFING - NO RECORD OF BRIEFING RECEIVED WEATHER BRIEFING - NO NORECORD OF BRIEFING RECEIVED WEATHER FORECAST - UNKNOWN/NOT REPORTED				
	SKY CONDITION OVERCAST		CEILING A	T ACCIDENT SITE	
	VISIBILITY AT ACCIDENT 2 MILES OR LESS	r site	-	TION AT ACCIDENT SITE	
	OBSTRUCTIONS TO VISION FOG TYPE OF FLIGHT PLAN NONE	N AT ACCIDENT SITE	TYPE OF W	EATHER CONDITIONS	