OAK77FA058 Page 1 of 1

NTSB Identification: OAK77FA058

14 CFR Part 91 General Aviation

Event occurred Sunday, September 25, 1977 in NO.LAS VEGAS, NV Aircraft: REPUBLIC RC-3, registration: N6734K

FILE	DATE	LOCATION	AIRCRAFT DATA				FLIGHT PURPOSE	PILOT DATA	
3-3358	TIME - 0	919	N6734K DAMAGE-DESTROYED				NONCOMMERCIAL PLEASURE/PERSONAL TRANSF	PRIVATE, AGE 41, 98 TOTAL HOURS, 39 IN TYPE, NOT INSTRUMENT RATED.	
	DEPARTURE POINT NO.LAS VEGAS,NV								
			FRESNO, CA						
	TYPE OF ACCIDENT			PHASE OF OPERATION					
	COLLIDED WITH: TREES				IN FLIGHT: CLIMB TO CRUISE				
	PROBABLE CAUSE(S)								
	PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING								
	PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING								
	MISCELLANEOUS ACTS, CONDITIONS - FLEW INTO BLIND CANYON								
	FACTOR(S) TERRAIN - HIGH OBSTRUCTIONS								
	IBERRAIN - HIGH OBSTRUCTIONS WEATHER - HIGH DENSITY ALTITUDE								
	WEATHER - HIGH DENSITI AHITTOUE WEATHER BRIFFING - BRIFFED BY FLIGHT SERVICE PERSONNEL, BY PHONE								
	SKY CONDITION				CEILING AT ACCIDENT SITE				
	SCATTERED						MITED		
	VISIBILITY AT ACCIDENT SITE						ITATION AT ACCIDENT SITE		
	5 OR OVER(UNLIMITED)					ONE			
	OBSTRUCTIONS TO VISION AT ACCIDENT SITE				TEMPERATURE-F				
	NONE				73				
	WIND DIRECTION-DEGREES				WIND VELOCITY-KNOTS				
	350				6				
	TYPE OF WEATHER CONDITIONS				TYPE OF FLIGHT PLAN				
	VFR				VFR				
	FIRE AFTER IMPACT								